



June 22, 2022

Product Advisory #1857

Part Numbers: EBX-38EAP, EBX-38EBP, and EBX-38ECP

This is a formal notification regarding products supplied by VersaLogic Corp. Our records indicate that your company has purchased one of these products.

Please read this notice thoroughly to determine what impact this change may have on you with regard to your currently owned product or future purchases from VersaLogic Corp.

Affected Products

Products	Description	Old Revision Level	New Revision Level
EBX-38EAP	"Viper" Single board computer	1.02A	2.00A
EBX-38EBP	"Viper" Single board computer	1.02A	2.00A
EBX-38ECP	"Viper" Single board computer	1.02A	2.00A

Changes Made to Products

The printed circuit board for this product was modified slightly to accommodate an equivalent component in the power supply circuit, for a component that is currently unavailable through standard distribution channels.

Customer Impact

None. The revised product will operate identically to the previous version.

Additional Information

For additional information or assistance related to this change, please contact VersaLogic Technical Support at Support@VersaLogic.com or call (503) 747-2261.