



# PRODUCT OBSOLESCENCE MEMO

## MAGNETICS



## Bourns® Model CI100505 Series Multilayer Chip Inductors to be Discontinued

Riverside, California – July 22, 2022 – In accordance with our ongoing product life cycle management procedure, Bourns will transfer the [Model CI100505 Series Multilayer Chip Inductors](#) to an End of Product Life status on April 22, 2023. A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is provided below:

Obsolete Part Numbers					
CI100505-10NJ	CI100505-1N2D	CI100505-2N2D	CI100505-3N9D	CI100505-68NJ	CI100505-LAB1
CI100505-12NJ	CI100505-1N5D	CI100505-2N7D	CI100505-47NJ	CI100505-6N8J	CI100505-R10J
CI100505-15NJ	CI100505-1N8D	CI100505-33NJ	CI100505-4N7D	CI100505-7N5J	
CI100505-18NJ	CI100505-22NJ	CI100505-39NJ	CI100505-56NJ	CI100505-82NJ	
CI100505-1N0D	CI100505-27NJ	CI100505-3N3D	CI100505-5N6D	CI100505-8N2J	

No replacement part numbers are available at this time.

Customers may continue to purchase the affected part numbers during the End of Product Life transition period between now and April 22, 2023. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **April 22, 2023**

Last time ship date: **April 22, 2024**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC22092